

评价报告网上公开信息表

过控编号	皖 WH20240800084		
项目名称	岳西县岔路口加油站安全现状评价（项目编号：AX2024013）		
项目简介	岳西县岔路口加油站位于岳西县冶溪镇桃阳村 X092 公路北侧，建于 2015 年 5 月，产权自有，占地面积 529.5m²，企业类型个体工商户，主要从事汽油、柴油零售业务。2020 年 12 月 29 日该站经安庆市商务局换发了成品油零售经营批准证书，批准证书号为：油零售证书第 皖 H1147 号。2021 年 11 月 8 日该站经安庆市应急管理局换发了危险化学品经营许可证，许可证登记编号为：皖庆危化经（甲）字〔2021〕000117 号，有效期至 2024 年 11 月 15 日。 岳西县岔路口加油站设置了双枪加油机 2 台（其中 95#汽油加油机 1 台，0#柴油加油机 1 台），双层埋地储罐 2 台（其中其中 0 # 柴油 30m³ 储罐 1 台，95 # 乙醇汽油 30m³ 储罐 1 台），油罐总容积 60m³，折合油罐容积为 45m³，为三级加油站。该加油站已设置加油、卸油油气回收系统。		
评价报告提交时间	2024 年 8 月 22 日		
一、参与人员			
承担的主要工作	姓名	安全评价师	注册安全工程师
项目负责人	何柏云	是	是
项目组成员	陶远	是	是
	何柏云	是	是
	伍宇	是	是
	谢丹	是	是
	杨正良	是	否
编制人	何柏云	是	是
审核人	胡江海	是	是
技术负责人	陈钟毓	是	是
过程控制负责人	刘姐	是	是
二、到现场开展工作情况			
人员	何柏云、谢丹	时间	2024.7.12 2024.7.29（复查）
主要任务	现场收集了项目基本信息，采集了现场影像资料，通过对项目周边环境及项目场地进行勘察，提出安全对策措施与建议，并对该项目是否符合国家法律法规等进行了判定。		
三、其他内容			
无			
备注：其他内容为安全评价机构认为有必要公开的内容。			

AX2024013 岳西县岔路口加油站安全现状评价项目影像资料

周边环境：

项目东侧民居楼及电力线



项目西侧民居楼及电力线



项目南侧X092公路及电力线



项目北侧山林



岳西县岔路口加油站全景照片



岳西县岔路口加油站罐区照片



The image shows a man in a white uniform and hard hat standing next to a blue emergency response card for the 'Guoxi Xinglu Road Jiajiu Station Emergency Disposal Card'. The card lists contact information for various departments and emergency services. To the right is a yellow warning sign that reads '油库重地 请勿入内' (Oil depot, no entry) and 'The oil depot powerhouse Do inside'.

岳西县公安局
加油站责任民警联系牌

民警姓名: 王强
手机号码: 13856222222
电子邮箱: 13856222222@163.com

岳西县公安局加油站应急处置卡

序号	应急处置措施
1	发现火情时, 立即报警, 并启动应急预案。
2	发现油罐泄漏时, 立即停止加油, 并疏散现场人员。
3	发现车辆起火时, 立即使用灭火器灭火, 并疏散现场人员。

